



## Flexi 'no edge' blending tape

*SPT 05*

- Foam tape helps blending out clear coats and 2K topcoats
- Can be used to avoid edge forming by applying primers
- Saves time when sanding primers and polishing clear coats
- Flexible application, also on round forms
- Easy to use for masking curves
- TIP: remove before drying to avoid glue residue



Code	Description	Box	Pal
SPT 05	Flexi no edge blending tape 15mm x 25m	1	210

